


Wiring Diagram — WD1-02

For External Rotor Motor Type

Single phase motor with capacitor and thermal contacts



U1 - Brown
U2 - Blue
Z1 - Black
Z2 - Orange

Note: TK/TB (when fitted) MUST be wired from the motor to a control device.

Ref. AS/NZS 300, 4.13.3.3 (b), (c).