


Wiring Diagram — WD3-02


THREE PHASE SINGLE SPEED MOTORS

Please refer to the motor nameplate for specific details of each motor

For Delta connected motors (generally those 4 kW and larger)



For Star connected motors (generally those 3 kW and smaller)



Incorrect connection will cause the motor to burn out and warranty will be void